
WIDE ANGLE ARROWHEAD

PARTS LIST

10	wide angle arrowhead	40	ferrule
10a-b	wide angle arrowheads	42	arrow shaft
12	mounting fixture	44	interior bevel
14	chisel point	46	interior wide angle
16	circular recess	48	centerline
		50	narrow angle blade
18	first shaft portion	52	chisel point
20	beveled ring	54	interior wide angle
22	second shaft	56a-b	blades
	-	58	wide angle
24a-n	slots	60a-b	blades
26	threaded shaft portion	62	interior wide angle
28a-n	blades		•
30	blade base edge		
32	blade cutting edge		
34	blade trailing edge		. *
36	blade capture protrusion		
38	blade capture point		






FIG. 2

